



MyHomeinspections

HOME INSPECTION

3BHK inspection

Skypark

CLIENT

Nagaraju Palivela

Yendada

PROJECT DESCRIPTION

own house

REPORT DATE

May 8, 2026

PREPARED BY

Rahul Palivela

REPORT ID: CDC43CCB-7C99-4842-B527-AF415AC75156

CONFIDENTIAL

Dimensions & Area Summary

TOTAL MEASURED

710 sq ft

METRIC EQUIVALENT

65.96 sq m

SPACES MEASURED

5

SPACE	UNIT	LENGTH	WIDTH	AREA
Living Room Open living and dining area with large front-facing windows, ceiling fan, and hardwood flooring.	ft	18	14	252 sq ft
Master Bedroom Primary bedroom with attached closet, queen-size bed layout	ft	14	12	168 sq ft
Bedroom 2	ft	12	11	132 sq ft
Bedroom 3	ft	11	10	110 sq ft
Bathroom 1	ft	8	6	48 sq ft



INSPECTION FINDINGS

SECTION 01 / TECHNICAL OBSERVATIONS

Checklist Exceptions

FAILED POINTS

3

MAJOR SEVERITY

1

PHOTOS ATTACHED


3

FAILED CHECKLIST ITEM



Observation 1

NO MINOR



CHECKLIST POINT

Electrical D.B. Work: Is the Voltage between 220 - 240 V?

CATEGORY
Living Room

INSPECTION TYPE
Home Inspection


FAILED CHECKLIST ITEM



Observation 2

NO

MAJOR



CHECKLIST POINT

Electrical D.B. Work: ELCB / RCCB MCB fitted & functioning

CATEGORY

Living Room

INSPECTION TYPE

Home Inspection

FAILED CHECKLIST ITEM



Observation 3

NO MINOR



CHECKLIST POINT

Doors: Door fittings are free from paint, dust and rust

CATEGORY
Master Bedroom

INSPECTION TYPE
Home Inspection



ISSUE REPORTS

SECTION 02 / ISSUES

1 Ceiling Plaster Crack & Paint Peeling

MEDIUM

OBSERVATIONS & NOTES

Visible plaster cracks and paint peeling observed on the living room ceiling near the corner joint. Minor dampness marks and surface deterioration indicate improper finishing or possible moisture seepage. Repair and repainting are recommended to prevent further damage.



LOCATION

Living Room Ceiling Corner

RESPONSIBLE ENGINEER

Rahul Palivela

VISUAL EVIDENCE



END OF REPORT

REPORT GENERATED BY REPORTGEN © 2026