Western Spares Hub Receiving Hold Root-Cause & Voicemail Transcript Audit

Audit ID: BGS-WEST-2026-AOG | Source: Western Hub Director Voicemail & Receiving Dock Inspection

1. Root Cause of the $14.8M Western Hub Receiving Hold (Voicemail Timestamp 00:42 - 01:35):
   - Physical spares inventory IS sitting on the Western Hub receiving dock ($14.8M across 112 pallets).
   - However, ERP receiving locked the lots in quarantine because 3 Tier-2 sub-suppliers shipped paper AS9100 Form 8130-3 airworthiness tags with mismatched heat-lot numbers after the ERP schema upgrade.
2. Voicemail Timestamp 01:36 - 02:18 (Buffer Stock Exhaustion Order):
   - 737 Thrust Reverser Actuators (TRA-500) exhaust buffer stock in 36 hours (first to stock out).
   - 787 Flight Control LRU housings (AV-7840) exhaust buffer stock in 48 hours (second to stock out).
3. COO Rebuttal if Finance Proposes Freezing the $3.2M Expedited Air-Freight Budget:
   - Freezing the $3.2M air-freight bridge while $14.8M of dock inventory is cleared will trigger $19.4M in mandatory airline AOG penalties within 72 hours. Deploy 6 DER quality engineers + OCR cert validation this weekend to release the $14.8M dock hold and sunset air-freight in 10 days.