

СОСАТЬ

Machine Coordinates

X 132.333 Y 100.000 Z -10.573

Work Coordinates

X 87.300 Y 67.393 Z -5.573

Auto Mode



Manual

MDI Mode

Active
G-command
G81 G54 G41

History

G00 X10 Y10 Z25
G01 F1000 S500 Z0

Enter MDI comand...

Send

Feed Override

1200



Rapid Override

100



Spindle Override

700




Jog Speed

120



Max Velocity

300



1
2
3
4
5
6
7
8
9

1
2
3
4
5
6
7
8
9