



CMC Bio Filter Service

Service Date: 6 September 2024

Work Completed

- Primary tank vacuumed by tanker
- Water pumping pumps (2no) lifted, cleaned, checked and returned to tank
- The bottom of the water tank was vacuumed as some silt deposits were building up
- Bio-filter pumps (3no) were extracted, cleaned, checked and returned back into tank
- The bio-filter consumer unit was found to have a fault that showed the SSR pump was not working. After investigations later that day with an electrician it was found that the timer switch was faulty and in turn a power surge knocked out the digital amp reader. The power surge could have come from the SSR pump if it started pulling more amps than it was designed for, but on testing the SSR pump works...for now.

I have ordered replacement components for the consumer unit, I will fit them hopefully early next week.

System Status

The system was left in partial working order pending replacement of the consumer unit components.

Engineer

Manny

Next Action

Replacement components for the consumer unit to be fitted early the following week.