

12_1012 - IGNITION SYSTEM-PLUG/PLUG/IGNITION COIL







NOTE: SINCE THE SPARK PLUG SOCKET HAS BEEN CHANGED, THE EXTRACTOR CAN LONGER BE USED:

2

\$130

02 **12 12 1 342 641** IGNITION WIRE 0.26 2 \$130



FOR VEHICLES WITH TOTAL ELIMINATION OF INTERFERENCES (CODE: X461A) FO VEHICLES WITH AUTHORITY VERSION:

02 **12 12 1 342 179** SUPPRESSED IGNITION WIRE (to 12/02) 0.28 2 \$200

AUTHORITY VEHICLES ONLY as this is a "suppressed ignition wire!

03 **12 12 2 306 064** ADAPTER (to 12/02) 0.01 1 \$2







04 **12 13 1 341 978** IGNITION COIL (to 12/02) 0.77 1 \$28







12 13 1 341 978 IGNITION COIL 0.77 1 \$28







FOR VEHICLES WITH TOTAL ELIMINATION OF INTERFERENCES (CODE: VEHICLES WITH AUTHORITY VERSION:				X461A) FC
04 12 13 1 342 178	IGNITION COIL WITH INTERFER.SUPPRESSION (to 12/02)	1.39	1	\$467
04 12 13 1 342 178	IGNITION COIL WITH INTERFER.SUPPRESSION	1.39	1	\$467
05 12 13 2 306 157	SCREW (to 12/02)	0.02	2	\$6
05 12 13 2 306 157	SCREW	0.02	2	\$(
•				
06 12 13 2 306 158	PLATE (to 12/02)	0.02	2	\$!
•				
06 12 13 2 306 158	PLATE	0.02	2	\$!
•				
07 07 11 9 900 510	WAVE WASHER - B7 (to 12/02)		2	\$3
07 07 11 9 900 510	WAVE WASHER - B7		2	\$(