


OFFICIAL ACCIDENT REPORT



Report Number	ACC-2026-899701	Report Date	June 15, 2026 19:54
Accident Location	—	Emirate	UAE
Accident Severity	Moderate	GPS Coordinates	—
Authorized Estimate	AED 641.04	Coverage	80.0%
Claim ID	claim_owner_1781538899701	Workshop	—

1. Incident Context & Conditions

Time of Incident	19:50	Road Type	Dry road
Weather Condition	Clear / dry	Lighting	Dawn / dusk — reduced visibility

Brief Description of Circumstances

The insured vehicle's bumper was struck by another vehicle. The incident occurred as a result of a collision. The damage was sustained to the rear of the insured vehicle. The circumstances of the incident have been reported.

AI damage evidence (pre-assessment only): Light — Lamp Crack (80%); Door — Scratch (65%); Fender — Scratch (89%); Scratch (77%); Part Crack (75%); Glass Crack (60%)

2. Vehicle 1 (Reporting / Liable Party)

Plate Number	ABU DHABI 4/ 88432	Vehicle Responsibility	100% Liable
Make & Model	MERCEDES-BENZ MERCEDES-BENZ-SEDAN-TEST (2024)	Policy / Insurer	OIC-AD-1122334455 Oman Insurance Company
Chassis Number (VIN)	WDDZF8DBXRA765432	Mulkiya Expiry	15-SEP-2026
Driver / Owner	Ahmed Ali	Garage Assigned	—

Identified Damage Areas

Light — Lamp Crack (Moderate, 80%); Door — Scratch (Minor, 65%); Fender — Scratch (Minor, 89%); Scratch (Minor, 77%); Part Crack (Moderate, 75%); Glass Crack (Moderate, 60%)

3. Vehicle 2 (Affected Party)

Plate Number	Pending verification	Vehicle Responsibility	0% Liable
Make & Model	Third party — details pending	Notes	Yes — other vehicle

First Party Signature

■■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)

Second Party Signature

■■■■■■■■ ■■■■■■ ■■■■■■ (■■■■■■■■)

AUTOVAULT Verification Authority



AUTOVAULT AI Platform · Traffic Systems Integration · Generated for insurer and workshop adjudication.