Sundaram Auto Care - Authorised Service Partner

12, Anna Salai, Chennai, Tamil Nadu - 600002 | Ph: 044-28451190 | GSTIN: 33AAKCS5678M1Z4

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.: JC-CHN-2026-5127	Date: 21 September 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:

Vijay M

Vehicle:

Kia Seltos HTX Plus

Registration No.:

TN-12-AJ-1603

Odometer Reading:

24,680 km

Chassis No. (VIN):

MA2022890123XX

Insurer / Policy No.:

Ganit Motors Insurance Co. Ltd. / POL-112233

Claim No. / Surveyor:

GMI/2026/CHN/041127 | S. Venkatesh, IRDAI SLA-No. 61204

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper Assembly (OEM)	Replace	1	OEM	11,500
2	Bonnet / Hood Panel (OEM)	Replace	1	OEM	14,200
3	Front Grille Assembly (OEM)	Replace	1	OEM	5,400
4	Headlight Assembly RH (LED Projector, OEM)	Replace	1	OEM	18,500
5	Front Right Fender	Repair + Paint	1	OEM	3,600
6	Radiator Assembly (OEM)	Replace	1	OEM	8,400
7	Labour - Panel Beating, Denting & Fitment	Labour	9.5 h	Rs.720/h	6,840
8	Labour - Painting (2-coat oven finish, 4 panels)	Labour	11.0 h	Rs.780/h	8,580

Sub-Total	Rs. 77,020
CGST @ 9%	Rs. 6,932
SGST @ 9%	Rs. 6,932
GRAND TOTAL	**Rs. 90,884**

Note: Severe front-right impact damage from a head-on collision with a roadside barrier. All parts OEM wherever possible. Repair scope matches damage survey and FIR.

Sd/- Vijay M
Customer Signature

Sd/- R. Krishnan
Authorised Signatory

(Vijay M) *(R. Krishnan, Service Advisor)*

SYNTHETIC SPECIMEN - generated by ClaimIntel for demonstration. Not a genuine commercial document.