

Heat Pump Health Check Report

Your personalised assessment from Integrity Heat Pumps

Your Details

Name	Wajahat Hafeez
Postcode	4400
Report Date	02/04/2026
Reference	REF-14316
Property Type	semi-detached
Bedrooms	3
Home Insulation	poor
Heat Pump Make / Model	YVL125A55CG

Overall Health Check Rating



AMBER — Performance Issues Detected

Some issues in airflow and ice buildup need attention.

Note: This free assessment is based on your photographs and questionnaire answers. It is not a substitute for an in-person inspection.

What We Found — Quick Checklist

Here is a summary of the key checks we carried out based on your photos and answers:

Check Item	Status
Outdoor unit airflow	⚠️ Issue Found
Outdoor unit cycling	✅ No Issues
Ice buildup / defrost	⚠️ Action Needed
Controller settings	✅ No Issues
Hot water tank	✅ No Issues
Pipework	✅ No Issues
Radiators & TRVs	✅ No Issues

✅ *OK* | ⚠️ *Action Needed* | ⚠️ *Issue Found*

The 3 Most Common Efficiency Killers

Based on your answers, here is how your system performs against the three issues we see most often:

- 💡 **Optimize Defrost Settings**

Review and optimize defrost settings to prevent ice buildup and maintain efficiency.
- 💡 **Regular Maintenance**

Ensure regular maintenance to prevent airflow blockages and improve overall system health.

Your Simple Action List

These are the quick wins we recommend you try first. They cost nothing and can make a noticeable difference to your comfort and bills:

- Increase clearance around the outdoor unit to at least 300mm on all sides, especially the fan outlet, by modifying or removing the surrounding structure.
- Verify hot water cylinder temperature settings to ensure it's not set excessively high and that an immersion heater (if present) is not activating unnecessarily.
- Check the outdoor unit — inspect the rear of the unit for any ice build-up. Some frosting is normal in cold weather, but a thick layer of ice that doesn't clear within an hour or two could indicate a defrost fault.
- Schedule a professional system health check and commissioning review by an MCS-certified engineer to ensure optimal performance and identify any minor inefficiencies.
- Check your hot water cylinder settings — if your 'Boost' or immersion heater is running daily, consider reducing the frequency or temperature to the minimum safe level (60°C).

Want to Go Deeper? Your Next Steps

This free report focuses on the most impactful quick wins. If you'd like a more detailed look at your specific heat pump setup — or you're still not getting the warmth or bills you expect — here's how we can help further:

	What You Get	Price
	FREE Health Check — you already have this!	FREE
	Performance Optimisation Report — a deeper dive into your specific setup, with tailored recommendations to cut your bills and improve comfort.	£39
	Home Visit & System MOT — a qualified engineer visits, checks everything in person, and follows up with a written action plan.	£350

To find out more or to book your *Performance Optimisation Report*, visit us at www.IntegrityHeatPumps.co.uk or reply to the email this report arrived in.

Disclaimer: This report is based solely on the photographs and questionnaire responses provided by the customer. Integrity Heat Pumps accepts no liability for actions taken on the basis of this report without a full in-person inspection.

All assessments are indicative only.

Integrity Heat Pumps | www.IntegrityHeatPumps.co.uk | This report is confidential to the named recipient.