
TRANSFORMATION MATRIX FOR A 30° CLOCKWISE ROTATION ABOUT THE Z-AXIS.

$$[T] = \begin{bmatrix} \cos\Theta_{xx} & \cos\Theta_{xy} & \cos\Theta_{xz} \\ \cos\Theta_{xx} & \cos\Theta_{yy} & \cos\Theta_{yz} \\ \cos\Theta_{zx} & \cos\Theta_{zy} & \cos\Theta_{zz} \end{bmatrix}$$

$$= \begin{bmatrix} 0.866 & -0.5 & 0\\ 0.5 & 0.866 & 0\\ 0 & 0 & 1 \end{bmatrix}$$

TRANSFORMING THE PRINCIPOL STATE OF STRESS 45° ABOUT THE 2-AXIS



$$\begin{bmatrix} T \end{bmatrix} = \begin{bmatrix} \cos\Theta x''_1 & \cos\Theta x''_2 & \cos\Theta x''_3 \\ \cos\Theta y'_1 & \cos\Theta y''_2 & \cos\Theta y''_3 \\ \cos\Theta z'_1 & \cos\Theta z''_2 & \cos\Theta z''_3 \end{bmatrix} = \begin{bmatrix} 0.7671 & 0 & -0.7671 \\ 0 & 1 & 0 \\ 0.7671 & 0 & 0.7671 \end{bmatrix}$$