Informe Núm.:D0106277991

Informe de inspección

Este informe ha sido creado por **LAUNCH**

Información del vehículo

VIN: LSFAM11A0MA053098
Marca/Modelo: Maxus/T60(XingJi L (D20))
Año fabricación: 2021
Cuentakilómetros: 74017
Versión de Software del Vehículo: V10.63
Estado de la reparación: 1

Entidad inspectora

Nombre:
Dirección:
Teléfono:
Núm Serie: 979794013543
Fecha y hora de la inspeccción: 2026-04-30 21:41:50

Resultado Inspección

Existen 20 puntos a revisar en Carrocería/Body sistemas:

1.Lost communication with Instrument Pack (IPK)
2.Abnormal communication between OBC and BMS CAN (598 or 603 message lost)
3.Signal comparison failure, VIN not equal to VIN in IPK
4.Lost communication with Instrument Pack (IPK)
5.Communication with Body Control Module (BCM) interrupted
6.ODO backup VIN code error
7.FHM LIN message no receive
8.Abnormal communication between OBC and BMS CAN
9.FL sensor not receiving corresponding RF signal (travel distance in 10 minutes larger than 20kph)
10.Rear right corner sensor signal line short to ground or open circuit
11.Rear right corner sensor aftershock time fault
12.Rear left corner sensor signal line short to ground or open circuit
13.Rear left corner sensor aftershock time fault
14.Lost communication with Steering Angle Sensor (SAS)
15.Lost communication with Body Control Module (BCM)
16.FHM LIN message no receive
17.Lost Communication With BMS
18.Lost Communication With IPK
19.Lost Communication With BMS

20.Signal comparison failure, VIN not equal to VIN in IPK

La inspección es normal en Carrocería/Body sistemas

1.Lane Departure Warning System (LDWS)
2.Front Headlamp System
3.Engine Management System (4K22 Mitsubishi 2.4 Gasoline Engine CN6)
4.TCCU (Transfer Case Control Unit)
5.ABS/ESP (Anti-lock Braking System or Electronic Stability Program) (ENS NLE 2.0 or EMS MT22 1 4G69)
6.Engine Management System (VM FGT/VGT EU5)
7.ABS(Anti-lock Brake System) or ESP(Electronic Stability Program)
8.ESC(Electronic Stability Control)double turbo engine
9.Engine Management System (D20)
10.Transfer Case Control Unit (BorgWarner)
11.Airbag
12.Engine Management System (VM FGT/VGT EU4)
13.Electronic Stability Program (9.3)
14.ECM (Engine Control Module) (D20) (23MY)
15.ABS9 (Anti-lock Braking System) Zhejiang Asia-Pacific

Informe Prueba Profesional

Lane Departure Warning System (LDWS) Normal

Front Headlamp System Normal

FICM (Front Infotainment Control Module) (CR) Anormal 2

Núm. DTC(2)

U0255-87	Lost communication with Instrument Pack (IPK) History DTC, Fault Light Off
U011187	Abnormal communication between OBC and BMS CAN (598 or 603 message lost) Generic type DTC,reference only

Engine Management System (4K22 Mitsubishi 2.4 Gasoline Engine CN6) Normal

Body Control System Anormal 1

Núm. DTC(1)

U0424-62	Signal comparison failure, VIN not equal to VIN in IPK

Current DTC, Fault Light Off

TCCU (Transfer Case Control Unit) Normal

Gateway Anormal 1

Núm. DTC(1)

U0155-87	Lost communication with Instrument Pack (IPK)

History DTC, Fault Light Off

Instrument Control Module (ICM) Anormal 2

Núm. DTC(2)

U0140-87	Communication with Body Control Module (BCM) interrupted

History DTC, Fault Light Off

U0210-00	ODO backup VIN code error

Current DTC, Fault Light Off

ABS/ESP (Anti-lock Braking System or Electronic Stability Program) (ENS NLE 2.0 or EMS MT22 1 4G69) Normal

Engine Management System (VM FGT/VGT EU5) Normal

Front Infotainment Control Module (Zebra Integrated machine) Anormal 2

Núm. DTC(2)

U025587	FHM LIN message no receive

Generic type DTC,reference only

U011187	Abnormal communication between OBC and BMS CAN

Generic type DTC,reference only

IPMS (Tire Pressure Monitor System) Anormal 1

Núm. DTC(1)

B1006-31	FL sensor not receiving corresponding RF signal (travel distance in 10 minutes larger than 20kph)

Current DTC, Fault Light On

Blind Spot Detection System Anormal 6

Núm. DTC(6)

B1D81-14	Rear right corner sensor signal line short to ground or open circuit	Current DTC, Fault Light Off
B1D82-76	Rear right corner sensor aftershock time fault	History DTC, Fault Light Off
B1D84-14	Rear left corner sensor signal line short to ground or open circuit	Current DTC, Fault Light Off
B1D85-76	Rear left corner sensor aftershock time fault	History DTC, Fault Light Off
U0126-87	Lost communication with Steering Angle Sensor (SAS)	History DTC, Fault Light Off
U0322-87	Lost communication with Body Control Module (BCM)	History DTC, Fault Light Off

ABS(Anti-lock Brake System) or ESP(Electronic Stability Program) Normal

ESC(Electronic Stability Control)double turbo engine Normal

FICM (Front Infotainment Control Module) - Tianbao Anormal 2

Núm. DTC(2)

U025587	FHM LIN message no receive	Generic type DTC,reference only
U011187	Lost Communication With BMS	Generic type DTC,reference only

Engine Management System (D20) Normal

Transfer Case Control Unit (BorgWarner) Normal

Airbag Normal

Engine Management System (VM FGT/VGT EU4) Normal

FICM (Front Infotainment Control Module) - Neusoft Anormal 2

Núm. DTC(2)

U025587	Lost Communication With IPK	History DTC, Fault Light Off
U011187	Lost Communication With BMS	Generic type DTC,reference only

Body Control System (BCM)(NLE 2.0) Anormal 1

Núm. DTC(1)

U0424-62	Signal comparison failure, VIN not equal to VIN in IPK	Current DTC, Fault Light Off

Electronic Stability Program (9.3) Normal

ECM (Engine Control Module) (D20) (23MY) Normal

ABS9 (Anti-lock Braking System) Zhejiang Asia-Pacific Normal

Descargo de responsabilidad

Este informe de la prueba es solamente para su referencia y está basado en la detección de los códigos de error y mantenimiento del vehículo. Toda la información suplementaria contenida en este informe está basada en datos estadísticos. La información dinámica detallada y/o de diagnosis debe ser leída mediante un equipo de diagnosis profesional. LAUNCH no es responsable de cualquier fallo o accidente provocado.