## We used an electric screwdriver to fix the screws







We encountered a challenge due to the lack of sufficient space on the original chassis to mount all the required components. To

overcome this issue, we designed and installed a second layer

similar to the original chassis. This additional layer provided us

with the necessary space to organize and securely fix the

electronic parts in a more efficient and systematic way

