

TO DO
-Main ROM socket pins are too wide (too far between cols)
-Add debug pin headers for SPI pins
-Add an additional VCC/GND header or two (scope, LCD power, etc.)

TITLE: Sound Card (65816)	REV: 1.1
Company:	Sheet: 1/1
Date: 2022 April 21 Drawn By: rehsd	