

Service report - SD50B-2026-10005 - 2026-03-12

Document service-report-sd50b-2026-10005-06 · revision 1 · effective 2026-03-12

Machine type:

Findings

Attended Depot North for SD50B-2026-10005. Fault history showed E-074 (Solution flow blocked) logged four times in the preceding week, each time clearing on restart.

Work carried out

1. Updated the charger profile to the setting for the fitted pack chemistry.

2. Advised

Parts used

- Panel filter and seal

- Float shut

Outcome

Left out of service pending a replacement pack. The site has been told not to return it to the floor.