

# Service report - SD50B-2026-10142 - 2026-06-03

Document service-report-sd50b-2026-10142-13 · revision 1 · effective 2026-06-03

Machine type:

## Findings

Called to Metro Logistics Centre. Reported symptom was poor water pickup on SD50B-2026-10142. Found the squeegee deflection uneven across the width and the left hand blade worn well past its limit.

## Work carried out

1. Updated the charger profile to the setting for the fitted pack chemistry.

2. Recalibr

## Parts used

- No parts used; adjustment only

- Brush set

## Outcome

Returned to service. The underlying cause is operational rather than mechanical: the machine is being put on charge hot at the end of a double shift.