

Service report ☒ SDM43-2026-10416 ☒ 2026-03-30

Document service-report-sdm43-2026-10416-03 · revision 1 · effective 2026-03-30

Machine types: SDM-43

Item numbers: 1.291-101.0

Serial numbers: SDM43-2026-10416

Site: depot-north

Findings

Attended Depot North for SDM43-2026-10416 at 1060 h. The panel filter was blinded across most of its area, which explains the loss of suction reported by T. Nakamura.

Work carried out

1. Advised the site on the charging temperature limit and left a copy of the procedure.
2. Cleared the debris from the brush drive and checked the shaft seal for damage.
3. Cleaned the float shut-off and the recovery tank breather, then flushed the suction path.

Parts used

- Panel filter and seal
- Drive plate

Outcome

Returned to service with a note on the machine log to re-measure the brushes at the next interval.