

Fault report - SDM43-2026-10416 - 2026-06-19

Document fault-report-sdm43-2026-10416-00 · revision 1 · effective 2026-06-19

Machine types: SDM-43

Item numbers: 1.291-101.0

Serial numbers: SDM43-2026-10416

Site: riverside-mall

Reported symptom

Machine SDM43-2026-10416 is pulling to one side, and the operators are compensating on the steering for the whole shift.

Site assessment

Possibly related to the hopper being overfilled on the previous shift.

Status

Open, with a temporary machine supplied to cover the round.