

Fault report - SWR120-2026-10006 - 2026-09-12

Document fault-report-swr120-2026-10006-06 · revision 1 · effective 2026-09-12

Machine types: SWR-120

Item numbers: 1.721-106.0

Serial numbers: SWR120-2026-10006

Site: city-hospital

Reported symptom

The brush deck on SWR120-2026-10006 is cutting out under load. It runs fine unloaded and trips within a minute of the deck being lowered.

Site assessment

Suspected filter blockage, but nobody on site is trained to remove it.

Status

Still in use on the warehouse floor only, kept off the polished areas.