

Service report - SD50B-2026-10005 - 2026-03-12

Document service-report-sd50b-2026-10005-06 · revision 1 · effective 2026-03-12

Machine types: SD-50B

Item numbers: 1.512-342.0

Serial numbers: SD50B-2026-10005

Site: depot-north

Findings

Attended Depot North for SD50B-2026-10005. Fault history showed E-074 (Solution flow blocked) logged four times in the preceding week, each time clearing on restart.

Work carried out

1. Updated the charger profile to the setting for the fitted pack chemistry.
2. Advised the site on the charging temperature limit and left a copy of the procedure.
3. Replaced the squeegee blade set and reset the deflection across the full width.

Parts used

- Panel filter and seal
- Float shut-off assembly

Outcome

Left out of service pending a replacement pack. The site has been told not to return it to the floor.