```
C:\>debug 1b.exe
-t.
AX-076A BX-0000 CX-0036 DX-0000 SP-0000 BP-0000 SI-0000 DI-0000
DS=075A ES=075A
                SS=0769 CS=076B IP=0003
                                            NV UP EI PL NZ NA PO NC
076B:0003 8ED8
                       MOV
                              DS,AX
-t
                CX=0036 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
AX=076A BX=0000
DS=076A ES=075A
                 SS=0769 CS=076B IP=0005
                                            NU UP EI PL NZ NA PO NC
076B:0005 B80000
                      MOV
                              AX,0000
-t
AX=0000 BX=0000
                 CX=0036 DX=0000 SP=0000
                                           BP=0000 SI=0000 DI=0000
                                            NU UP EI PL NZ NA PO NC
DS=076A ES=075A
                 SS=0769 CS=076B IP=0008
076B:0008 BB0000
                       MOV
                              BX,0000
-t.
AX=0000 BX=0000
                CX=0036 DX=0000 SP=0000
                                           BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                 SS=0769 CS=076B IP=000B
                                            NU UP EI PL NZ NA PO NC
076B:000B B90000
                       MOV
                              CX,0000
AX=0000 BX=0000
                CX=0000 DX=0000 SP=0000
                                           BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B IP=000E
                                            NU UP EI PL NZ NA PO NC
976B:000E BA0000
                      MOU
                              DX,0000
-t
AX=0000 BX=0000 CX=0000 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A SS=0769 CS=076B IP=0011
                                            NU UP EI PL NZ NA PO NC
976B:0011 8D360000
                      LEA
                              SI,[0000]
                                                                DS:0000=1007
-t
AX=0000 BX=0000
                CX=0000 DX=0000 SP=0000
                                           BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B IP=0015
                                            NU UP EI PL NZ NA PO NC
076B:0015 8A04
                      MOV
                              AL,[SI]
                                                                DS:0000=07
-t
AX=0007 BX=0000 CX=0000 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B
                                  IP=0017
                                            NU UP EI PL NZ NA PO NC
076B:0017 46
                       INC
                              SI
-t
                CX=0000 DX=0000 SP=0000
AX=0007
        BX=0000
                                           BP=0000 SI=0001 DI=0000
                                            NU UP EI PL NZ NA PO NC
DS=076A ES=075A
                SS=0769 CS=076B IP=0018
976B:0018 8A1C
                      MOV
                              BL,[SI]
                                                                DS:0001=10
```

```
AX=0007 BX=0010 CX=0000 DX=0000 SP=0000 BP=0000 SI=0001 DI=0000
DS=076A ES=075A SS=0769 CS=076B IP=001A
                                           NV UP EI PL NZ NA PO NC
076B:001A F6E3
                      MUL
                              BL
-t
AX=0070 BX=0010 CX=0000 DX=0000
                                 SP=0000 BP=0000 SI=0001 DI=0000
DS=076A ES=075A SS=0769 CS=076B
                                  IP=001C
                                           NU UP EI PL NZ NA PO NC
076B:001C 46
                       INC
                              SI
-t
AX-0070 BX-0010 CX-0000 DX-0000 SP-0000 BP-0000 SI-0002 DI-0000
DS=076A ES=075A SS=0769 CS=076B IP=001D
                                           NV UP EI PL NZ NA PO NC
076B:001D 8AOC
                      MOV
                              CL,[SI]
                                                               DS:0002=12
-t
AX=0070 BX=0010 CX=0012 DX=0000 SP=0000 BP=0000 SI=0002 DI=0000
                SS=0769 CS=076B IP=001F
                                           NU UP EI PL NZ NA PO NC
DS=076A ES=075A
076B:001F 02C1
                      ADD
                              AL,CL
-t
AX=0082 BX=0010 CX=0012 DX=0000 SP=0000 BP=0000 SI=0002 DI=0000
                SS=0769 CS=076B
DS=076A ES=075A
                                  IP=0021
                                           OV UP EI NG NZ NA PE NC
076B:0021 46
                      INC
                              SI
```

```
AX=0082 BX=0010 CX=0012 DX=0000 SP=0000 BP=0000 SI=0003 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B IP=0022
                                           NU UP EI PL NZ NA PE NC
076B:0022 8A14
                      MOV
                             DL,[SI]
                                                               DS:0003=16
-t
AX=0082 BX=0010 CX=0012 DX=0016 SP=0000 BP=0000 SI=0003 DI=0000
DS=076A ES=075A SS=0769 CS=076B IP=0024
                                           NU UP EI PL NZ NA PE NC
076B:0024 ZBCZ
                      SUB
                              AX.DX
−t.
AX=006C BX=0010 CX=0012 DX=0016 SP=0000 BP=0000 SI=0003 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B IP=0026 NV UP EI PL NZ AC PE NC
076B:0026 00508B
                      ADD
                              [BX+SI-75],DL
                                                               DS:FF9E=F2
-t
AX=006C BX=0010 CX=001Z DX=0016 SP=0000 BP=0000 SI=0003 DI=0000
                SS=0769 CS=076B
                                           NV UP EI PL NZ NA PO CY
DS=076A ES=075A
                                 IP=0029
076B:0029 46
                      INC
                              SI
-t
AX=006C BX=0010 CX=0012 DX=0016 SP=0000 BP=0000 SI=0004 DI=0000
                SS=0769 CS=076B IP=002A NU UP EI PL NZ NA PO CY
DS=076A ES=075A
                      CLD
076B:002A FC
```