C:\>debug 5.exe -t		
AX=076A BX=0000 DS=075A ES=075A 076A:0003 BED8 -t	SS=0769 CS=076A IP=0003	BP-0000 SI-0000 DI-0000 NV UP EI PL NZ NA PO NC
AX=076A BX=0000 DS=076A ES=075A 076A:0005 BA0800 -t		BP=0000 SI=0000 DI=0000 NV UP EI PL NZ NA PO NC
AX=076A BX=0000 DS=076A ES=075A 076A:0008 B000 -t	CX=001E DX=0008 SP=0000 SS=0769 CS=076A IP=0008 MOU AL,00	
AX=0701 BX=0001 DS=076A ES=075A 076A:0012 02C3 -t	SS=0769 CS=076A IP=0012	BP=0000 SI=0003 DI=0000 NU UP EI PL NZ NA PE NC
AX-0702 BX-0001 DS-076A ES-075A 076A:0014 8804 -t	CX=001E DX=0007 SP=0000 SS=0769 CS=076A IP=0014 MOV [SI],AL	
AX=0702 BX=0002 DS=076A ES=075A 076A:0018 8A1C -t		
AX=070Z BX=0003 DS=076A ES=075A 076A:001A 4A		BP=0000 SI=0004 DI=0000 NU UP EI PL NZ NA PE NC
AX=0705 BX=0003 DS=076A ES=075A 076A:0014 8804 -t		BP=0000 SI=0005 DI=0000 NV UP EI PL NZ NA PE NC DS:0005=BA
AX-0705 BX-0003 DS-076A ES-075A 076A:0016 8AC3 -t	CX=001E DX=0005 SP=0000 SS=0769 CS=076A IP=0016 MOV AL,BL	
AX=0703 BX=0003 DS=076A ES=075A 076A:0018 8A1C -t		BP=0000 SI=0005 DI=0000 NV UP EI PL NZ NA PE NC DS:0005=05

	SS=0769 CS=076A IP=0014 MOV [SI],AL	
	CX=001E DX=0003 SP=0000 SS=0769 CS=076A IP=0016 MOU AL,BL	
DS=076A ES=075A	CX=001E DX=0003 SP=0000 SS=0769 CS=076A IP=0018 MOV BL,[SI]	
DS=076A ES=075A	CX=001E DX=0002 SP=0000 SS=0769 CS=076A IP=001A DEC DX	
	CX=001E DX=0001 SP=0000 SS=0769 CS=076A IP=001B JNZ 0011	
DS=076A ES=075A	CX=001E DX=0001 SP=0000 SS=0769 CS=076A IP=0011 INC SI	
	CX=001E DX=0001 SP=0000 SS=0769 CS=076A IP=0012 ADD AL,BL	
	CX=001E DX=0001 SP=0000 SS=0769 CS=076A IP=0014 MOV [SI],AL	
	CX=001E DX=0000 SP=0000 SS=0769 CS=076A IP=001B JNZ 0011	
	CX=001E DX=0000 SP=0000 SS=0769 CS=076A IP=001D INT 3	

AX=070D BX=0008 CX=001E DX=0003 SP=0000 BP=0000 SI=0007 DI=0000