

[illegible]

Diagram of J4 connector pinout:

- Pin 1: VBAT
- Pin 2: (Blue X)
- Pin 3: (Blue X)
- Pin 4: (Blue X)
- Pin 5: GND

Connector: J4 Conn_01x05

J1
Conn_02x03_Counter_Clockwise

PWM_DROP2 1 6
PWM_DROP1 2 5
+5V 3 4
GND

Diagram of J2 connector wiring. The connector has three pins: 1 (top), 2 (middle), and 3 (bottom). Pin 1 is connected to GND. Pin 2 is connected to +5V. Pin 3 is connected to HALL_SENS2.

Sheet: /		D
File: PCB_Droppers_2026.kicad_sch		
Title:		
Size: A4	Date:	
KiCad E.D.A. 10.0.3		Rev:
		Id: 1/1