

Product: RTL8188C/8192C/8192D USB Software Package - Linux Driver

Version: v3.3.1_3083.20111213

Release History:

Teleuse History.	I
v2.0.939.20100726	1. Use the bg mode when AP is in WEP and TKIP mode.
	(Recommended by latest WiFi 11n test plan).
	2. First release.
v2.0.967.20100730	1. Add functionality of Antenna diversity.
v2.0.974.20100803	1. Fixed the Big Endian issue.
v2.0.1042.20100902	1. Resolved static link issue with RTL8712U.
	2. Fixed the Ad-hoc connection bug when the Ad-hoc ssid
	is the same with someone AP's SSID.
	3. Update related PHY parameters to improve throughput.
	4. Improve Antenna diversity algorithm.
v2.0.1126.20101020	1. Added USB's selective suspend feature.
	2. Added the Realtek GPL into each C and header files.
	3. Added related ioctrl command for Android platform.
	4. Fixed NIC status display issue.
	5. Fixed power training issue at station mode.
v2.0.1170.20101112	1. Modify the CONFIG section of Android-x86
	2. Fixed radius issue.
	3. Update FW to V60.
	4. Support the Power saving function.
	5. Update usb_id_table to v38.
	6. Fixed the kernel panic when receive WDS packet.
v2.0.1180.20101116	1. Fixed compiler error.
v2.0.1212.20101205	1. Fix the Android private wifi ioctl SCAN-ACTIVE,
	SCAN-PASSIVE
	2. Alter the retry limit of "Active disconnect" to 8
	3. Fix the overkilling problem of active disconnect caused
	by frequently site surveying
	4. Fix the connect/disconnect looping problem on
	Android.
	5. Removed the "scan interval" protection of site survey
	function temporarily
	6. Adjust locking mechanism of TX, and fix
	race-condition issue.
v2.0.1212.20101208	1. Add Kconfig.
v2.0.1324.20110126	1. Synchronization strategy improved.
	2. Fixed the AP Tx fragment issue when using the
	WPA2-RADIUS.
	3. Added the IP header 8 bytes alignment.
	4. Added new feature - Easy Replacement.
	5. Added 20/40 MHz Coexistence test item (5.2.48 for wifi
	test)
	6. Fixed related connection failure issue in Ad-hoc mode.
20101620110211	7. Updated usb_id_table to DID_USB_v47_20110118.
v2.0.1346.20110214	1. Fixed Ad-hoc connection issues.



v2.0.1406.20110309	1. Updated usb_id_table to DID_USB_V50_20110209.
	2. Fixed compile error in kernel 2.6.37
	3. Fixed Ad-hoc issue with DLink-DWA130.

v3.0.1590.20110511	1. The version of usb_id_table is
	DID_USB_V60_20110425.
v3.0.1684.20110525	1. Add wps probe req ie & wps assoc resp ie for wps2.0
	2. Patch issue_qos_nulldata()/issue_nulldata() to set
	tods/fromds bit field depend on sta mode, ap mpde, adhoc
	mode
v3.0.1759.20110601	1. Supported the WiFi Direct functionality.
	2. Supported the WPSv2.0 functionality.
	3. Updated the hostapd and wpa_supplicant for WiFi
	Direct and WPS v2.0.
v3.0.2028.20110629	1. Refine WiFi Direct.
	2. Support Android wifi cmd "COUNTRY".
	3. Add HW antenna diversity function.
	4. Modified set wep key for auth SHARED mode.
	5. Modified key index for Broadcom IOT issue.
	6. Fixed Big Endian issue in amsdu_to_msdu().
	7. Support more USB dongle (DID_USB_V71_20110628).
v3.0.2052.20110701	1. Fixed the problem of cannot power down.
	2. Support Android early suspend
v3.0.2164.20110715	1. Reset MCU while polling FW ready fail
	2. Refine of RX signal statistics
	3. Support combo scan.
v3.0.2230.20110728	1. WiFi Direct function improve.
	2. Refine power saving functions.
v3.1.2291.20110804	1. Fixed WPS ie parsing issue.
	2. Add an ioctl rtw_p2p_get_device_name() that can get
	peer devices' names.
	3. Refine ioctls' set/get forms that related to p2p.
v3.1.2497.20110906	1. For SoftAP mode, fixed WPS connecting issue with
	RALINK3070.
	2. Fixed the Big Endian Autoload check fail issue.
	3. Fixed the IOT issue with Cisco 802.1x ap.
v3.1.2590.20110922	1. Fixed incorrect LED behavior.
	2. Fixed a potential resource leaks.
	3. Fixed possible race condition when using incorrect
	lock.
v3.1.2590.20111020	Sync. WiFi_Direct_User_Interface to driver
v3.3.0_2971.20111128	1. Support both CU-series and DU-series
	2. Supported Linux kernel v3.0.2
	3. Improved quality of Video over IP multicast
	4. Increase a functionality to support L2 Bridge
	5. Speed up hardware initialization process for CU-series
	6. Update android_reference_code
	7. Fixed some Endianness issues
	8. Fixed the IOT issue for Wi-Fi Direct connection,
	software AP and station mode
	9. Fix the roaming problem



v3.3.1_3083.20111213 1. Fix WEP SHARED connection problem.





Description:

Realtek provides the solution for WLAN in hardware and software. The software package could be adopted for Realtek RTL8188C/8192C/8192D USB WLAN series hardware on Linux based platforms.

Software Version:

RTL8188C/8192C/8192D USB Linux Driver Version: v3.3.1_3083.20111213

Firmware Version:

Firmware is embedded in the RTL8188C/8192C/8192D USB driver.

The firmware version of RTL8192C is V79

The firmware version of RTL8192D is V25

Hardware Supported:

CU-series:

- RTL8188CUS
- RTL8188RU
- RTL8188CUS-Slim Solo
- RTL8188CUS-Slim Combo
- RTL8188CE-VAU
- RTL8188CUS-VL
- RTL8188CTV
- RTL8192CUS
- RTL8192CE-VAU

DU-series:

- RTL8192DU-VS
- RTL8192DU-VC

Platform Supported:

- Linux (kernel 2.6.18 ~ 2.6.38 and kernel 3.0.2)
- Android 1.6 ~ 2.3

CPU supported:

- x86
- ARM
- MIPS