

Standard Operating Procedure: Quality Audit for Production Line B

Document No: SOP-QA-014 | Revision: 3 | Effective Date: 2026-01-15

1. Purpose

This procedure defines the steps required to conduct a quality audit on Production Line B, covering raw material inspection, in-process checks, and final product verification before release to the warehouse.

2. Scope

Applies to all Quality Assurance auditors and Line B production supervisors. Excludes Production Lines A and C, which follow SOP-QA-012 and SOP-QA-013 respectively.

3. Audit Frequency

Routine audits are conducted weekly, every Monday at 08:00. Unscheduled audits may be triggered by a customer complaint, a non-conformance report (NCR), or a request from the Plant Manager.

4. Audit Procedure Steps

Step 1: Verify that the production line log matches the master schedule for the current shift. Any discrepancy must be recorded as a deviation.

Step 2: Inspect a random sample of 15 units from the current batch using the dimensional checklist QA-FORM-09. Reject the batch if more than 2 units fail.

Step 3: Check that all operators on shift have a valid and current safety certification on file. Flag any expired certification to HR within 24 hours.

Step 4: Review the calibration sticker on all measurement tools used on the line. Tools with calibration overdue by more than 7 days must be pulled from service immediately and sent to the metrology lab.

Step 5: Document all findings in the Audit Report Form QA-FORM-11 and submit to the QA Manager within 4 hours of audit completion.

5. Responsibility Matrix

Role	Responsibility
QA Auditor	Conduct audit, complete QA-FORM-11
Line Supervisor	Provide access, production logs
QA Manager	Review findings, approve/reject batch
Plant Manager	Escalation point for repeated failures

6. Non-Conformance Handling

If a batch is rejected during audit, the Line Supervisor must quarantine the affected units within 1 hour and initiate NCR-FORM-02. Production may resume only after QA Manager sign-off on corrective action.