

Vendor Technical Report — P-102 Condition Review

Document ID: APEL-VND-P102-501 | Owner: Procurement | Revision: 1.0

ApexFlow Engineering was asked to comment on the P-102 condition.

Inputs

- 2026 inspection summary
- Pump model data
- Selected readings
- Maintenance history extract

Vendor observations

The vendor identified elevated vibration and localized casing corrosion.

Observations

- Vibration above historical baseline.
- Localized corrosion.
- Seal-area residue.
- No evidence establishing internal structural failure.

Operating pressure conflict

The vendor report includes a 45 bar operating reference that conflicts with the internal 40 bar limit.

Conflict

- Vendor reference: 45 bar.
- Internal approved maximum: 40 bar.
- PSV set pressure: 47.5 bar.
- Vendor reference does not override internal controlled practice.

Vendor recommendation

The vendor recommends detailed mechanical review and pressure verification.

Suggested actions

- Check alignment.
- Verify pressure indication.
- Assess corrosion location.
- Review seal condition.

Procurement interpretation

The vendor report is supporting evidence, not the governing internal operating procedure.

AI rule

- Cite the vendor claim.
- Cite the active internal limit.
- Expose the conflict.
- Do not average values.