

Reflection

What Went Well

Accurate drilling and clean layout — the grid lines held up throughout the process.

Challenges

Keeping pip spacing perfectly even and drilling consistently straight were the toughest parts.

Improvements

Better surface finishing and deeper, more uniform countersinks would elevate the final result.

