

UI/UX Lab Assignment

Bad Design Analysis in VIT Vellore Campus

Name: RISHI P M

Reg No: 23MIS0260

Course: UI/UX Lab

1. Flooding in Subway During Heavy Rain



Figure: Photograph of the identified bad design.

Bad Design:

The pedestrian subway connecting the hostel and academic blocks gets flooded during

heavy rainfall due to inadequate drainage. Water accumulation makes the subway unsafe, slippery, and difficult to use, forcing students to wait or take alternative routes.

Suggested Solution:

- Install a proper storm-water drainage system.
- Increase the slope of the floor toward drainage channels.
- Perform regular drain maintenance before monsoon.
- Add water-level sensors and warning signs during flooding.

2. Poor Campus Connectivity Due to Railway Track




Figure: Photograph of the identified bad design.

Bad Design:

Although the hostel and academic block are only about 100 meters apart in a straight line, the railway track running through the campus forces students to take a long detour of over 600 meters via the subway. This increases walking time and reduces accessibility.

Suggested Solution:

- Construct a pedestrian skywalk or foot overbridge across the railway track.
- Improve campus planning to minimize unnecessary travel distance.
- Provide clear wayfinding and shaded walkways.

3. Clumsy Staff Room Layout




Figure: Photograph of the identified bad design.

Bad Design:

The staff room has a confusing layout with closely packed cabins, making it difficult for students to locate faculty members. The waiting area has poor ventilation and lacks fans, creating an uncomfortable experience.

Suggested Solution:

- Redesign the layout with wider corridors and clearly numbered cabins.
- Install directory boards and signage at the entrance.
- Improve ventilation with exhaust fans and ceiling fans.
- Create a comfortable student waiting area with seating.