

 VALUE INTEGRATOR	PRODUCTION WORK INSTRUCTIONS	SOP No: PW236
	R6558-12KK1 Packing Operation	Rev: REV: 00
		Date: 11 OCT 2025

No.	INSTRUCTIONS	VISUALS	KEY POINTS / CONTACTS
1.	<ul style="list-style-type: none"> Operators must wear full PPE <i>Apron, only applicable to SQ operators</i> 	 <p>The diagram illustrates the required Personal Protective Equipment (PPE) for operators. It features a central figure of a person wearing a yellow high-visibility vest over a blue long-sleeved shirt, black trousers, and a white hard hat. Lines connect various icons to specific parts of the PPE:</p> <ul style="list-style-type: none"> Top left icon: Hard Hat Top right icon: Gloves Middle left icon: Apron Middle center icon: Safety Glasses Middle right icon: Ear Protection Bottom left icon: Work Boots Bottom center icon: Safety Shoes Bottom right icon: Safety Harness <p>PPE REQUIRED AT THIS AREA</p>	

Controlled By:	Maintenance	Approved By:	Zondi, Ndumiso	Page 1 of 1
Date: Saturday, October 11, 2025				

UNCONTROLLED WHEN PRINTED WITHOUT RED CONTROLLED STAMP & SIGNATURES