VoltCo Field Troubleshooting Guide (Bilingual)

English procedure: If error E203 occurs, verify ground bonding before replacing contactor.

Safety warning: Never bypass the protective earth connector during test.

Bilingual note: Ground insulation check requires minimum 500 V DC test voltage.