## Air Quality Control Environmental, Inc.



3640 NW 118 Avenue #3 Coral Springs, FL 33065

Phone: 954. 345.5821/954-752-4085 Fax: 954.341.9070



"If it's in your ducts...it's in your lungs!"

## **Proposal**

October 1, 2012

Racquet Club at Bonaventure 193,195,197,201,205,209 Lakeview Drive Weston, FL 33326

Re: Dryer Vent and Dryer Stack Cleaning Description and Scope of Work:

- 1. Remove all 60 dryer stack cover on roofs to facilitate cleaning.
- 2. Remove all lint, debris, etc. in each individual stack.
- 3. All individual apartments (60) will have cleaning performed on dryers and dryer vents leading to main dryer vent stacks.

## **Notes:**

- 1. All power vacuum equipment used is HEPA rated 99.97% per NADCA Standards using source removal methods.
- 2. Access parts needed to facilitate cleaning will be sealed and secured according to **SMACNA Standards**

60 stacks and 60 individual dryer vents \$85.00 each

Total Cost: \$5,100.00

**TERMS:** Balance due in full upon completion/annual service agreement will be available for 90 days after contract is signed.

Recommendations: The cost to replace dryer hoses and metal clamps to code standards would be additional \$35.00 per unit.(not included in this contract) This would be done only as needed depending on condition of dryer hoses located behind each dryer.

Submitted by Allan M. Dexter, Jr., CVI (Certified Ventilation Inspector)

· Need to give: dates of scheduling · Not to exceed of total