
CCS Breathalyser


CCS Breathalyser


- Sensor not attached



CCS Breathalyser

- Once sensor is attached/detected, measurement screen is displayed
- Press START to perform measurement







 Do not expose device to gas source during 20 seconds of warm up period




- Countdown during measurement
- Breathe on sensor during countdown period







- Advanced mode




- Main screen will show final result in PPM
 - Hold the result number to switch to display result in different unit




- Main screen will show final result in mg/l
 - Hold the result number to switch to display result in different unit




- Main screen will show final result in mg/100ml
 - Hold the result number to switch to display result in different unit




- Main screen will show final result in BAC mg/ml
 - Hold the result number to switch to display result in different unit




- Main screen will show final result in BAC %
 - Hold the result number to switch to display result in different unit



 After performing measurement, it is recommended to pause for 2 minutes before starting a new measurement




Display dialog when sensor is still cooling down






Indications

Green background when < 130ppm




Indications

Amber background when >= 130ppm



Indications


Red background when above 286ppm



Options

Options


- Long press on START to bring additional measurement menu
- Choose "Calibration" to perform calibration test:
 - During calibration, breathe normally on sensor
 - Only perform calibration when sober
 - Calibration is same as breathalyser, except the final result will to stored and used for compensation on future breath measurements
- Choose "Coefficient" to alter default coefficient values
 - Default coefficient values are only used when there is no calibration data available.
- Choose "Reset" to reset calibration data and coefficient values



Measurement History

Measurement History


 If historical data is available, an action icon will be displayed on top right corner of screen. Click on icon to display history data.



Measurement History

Measurement history





- Press step 1 to start calibration




- Wait for 20 seconds warmup period
 - Do no expose DUT to gas source



 Expose DUT to OPPM gas source or sober breath



Calibration Completed



 Failure message is displayed if breath not detected during measurement

