

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 26/04/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|------------------|--|--|----------------------|----------------------|--|
| 1 | OHP | BRC on co 34 | LT not working | drive tripped on ol reset done | 07:10:00 | 07:30:00 | |
| 2 | OHP | co-33m brc | LT not working | wrong complaint | 08:25:00 | 08:45:00 | |
| 3 | CHP | cc-35 S-1 | do drives starting | main in off made on | 06:40:00 | 07:00:00 | |
| 4 | СНР | cc-35 | BRS not healthy | fuse blown in CJB replaced and JOD also acted reset done | 06:30:00 | 07:00:00 | |
| 5 | CHP | cc-40 scr-6 | luff up not working | luff up limit stuckmade free | 08:30:00 | 09:25:00 | |
| 6 | CHP | cc-33 scr-4 | Lt not working drive tripping due to jamming | informed operation for cleaning | 12:30:00 | 12:50:00 | |
| 7 | CHP | cc-39 | direct mode remove request | removed | 13:00:00 | 13:05:00 | |
| 8 | CHP | cc-104 scr -9 | signal missing and no drive running | plc power recycled drives tested ohp side boom position limit problembypassed in io rack reclaiming mode also not coming bypassed in io rackslew oil cooler output flickering made on with pump on | 10:45:00 | 11:45:00 | reclaiming mode position to ohp side and oil cooler output to be checked later |
| 9 | WT | op-7 | breaker tripped | made on | 11:05:00 | 11:20:00 | |
| 10 | WT | ot-2 | drive 2 tripped in PGF1 fault | reset done | 11:05:00 12:00:00 | 11:10:00 12:05:00 | |
| 11 | IOSA | L&T wobr | main not getting on | auxiliary and control was in off made on | 07:40:00 | 07:55:00 | |