

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 25/08/2025

Shift: C

Incharge(s): Lal Singh

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|---------------------|---|--------------------------------|----------|----------|----------------------|
| 1 | OHP | CO21 | BRS bypassed as per operational requirement | bypassed | 01:10:00 | 01:20:00 | |
| 2 | OHP | TIS 5 on CO25 | Bypassed as per operational request | bypaased | 02:00:00 | 02:20:00 | |
| 3 | OHP | VF8a | Chute vibrator MPCB trip | Reset and made on | 23:40:00 | 23:45:00 | |
| 4 | CHP | CC-34 SCR-2 | LUFF OIL TEMPERATURE | KEPT IN CKT | 22:30:00 | 22:40:00 | |
| 5 | CHP | SCR-10 ON CC-105 | BC MPD TRIPPED ON EF | RESET DONE AND TESTED | 03:30:00 | 03:45:00 | |
| 6 | CHP | CC-40 | BRS UNIT NO POWER FUSE blown | REPLACED AND TESTED | 02:50:00 | 03:10:00 | |
| 7 | CHP | CC-37 S-1 | SIGNAL MISSING FREQUENTLY | SCR-2 USED AS repeater FOR S-1 | 22:30:00 | 22:50:00 | |
| 8 | CHP | CC-113 | STOPPED ON ZSS | PULLY SLIPPING | 05:15:00 | 05:25:00 | |
| 9 | CHP | CC28 | chute sensor malfunctioning due to rain | Bypassed | 04:45:00 | 04:44:00 | may check further |
| 10 | WT | OP-2 | BOTTOM PAD C AND U CLAMP PROBLEM | CHANGED | 22:00:00 | 23:00:00 | |
| 11 | WT | CO3 belt | olr acted | reset done | 04:45:00 | 04:50:00 | |