



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 15/01/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|---|----------|----------|----------|
| 1 | OHP | co 67 | olr acted | reset | 08:25:00 | 08:30:00 | |
| 2 | OHP | co 26 | olr acted | reset | 09:15:00 | 09:25:00 | |
| 3 | OHP | TIS 2 | failed to start,push button problem | push button replaced | 08:30:00 | 08:50:00 | no delay |
| 4 | CHP | CC 39 SCR6 | all drive not working,main contactor not pickup,ePB @operator cabin NO contact problem | bypassed contact and informed G shift | 08:30:00 | 08:40:00 | |
| 5 | CHP | CC 201 | olr acted | reset | 08:55:00 | 09:00:00 | |
| 6 | CHP | CC35 scr3 | b/c not running,olr acted | reset | 09:25:00 | 09:35:00 | |
| 7 | CHP | CC 32 | yard conveyor not working,mpd tripped | reset | 08:10:00 | 08:15:00 | |
| 8 | CHP | CC 51 | MPD acted 3 times | reset | 07:20:00 | 07:25:00 | |
| 9 | CHP | CC 131 | olr acted | reset | 13:45:00 | 13:50:00 | |
| 10 | WT | CT | communication problem | modem replaced,and configuration done in modem | 06:00:00 | 06:45:00 | |
| 11 | WT | OP4 | no movement,communication problem | LC1 and LC2A side modem power recycle done and ethernet cable plugged and unplugged | 13:30:00 | 14:00:00 | |