



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/11/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|---------------------------------|----------|----------|----------------------|
| 1 | OHP | BRC on CO 30 | b/c olr acted | reset | 23:50:00 | 00:00:00 | |
| 2 | OHP | CO 19 TBS | Left bc not running,stopping in zss,sometimes | zss bypassed | 00:00:00 | 00:30:00 | module to be checked |
| 3 | OHP | CO 29 | OLr acted | reset | 03:50:00 | 04:00:00 | |
| 4 | OHP | CO 62(B) | mpcb tripped due to jamming | made on | 01:00:00 | 01:05:00 | |
| 5 | OHP | TIS 1 on co 5 | not healthy,emergency acted by mechanical, v belt problem | bypassed and emergency released | 23:40:00 | 00:00:00 | |
| 6 | OHP | TIS 2 | not healthy,emergency acted by mechanical, | emergency released | 02:00:00 | 02:10:00 | not electrical delay |
| 7 | OHP | TIS 3 | not healthy,power mpcb tripped | made it on | 02:10:00 | 02:15:00 | |
| 8 | OHP | CO 11 | chute sensor acted,earth fault | bypassed | 04:10:00 | 04:15:00 | checking going on |
| 9 | CHP | CC 51 | mpd acted | reset | 00:45:00 | 00:50:00 | 2 times |
| 10 | CHP | CC 131 | olr acted | reset | 00:01:00 | 05:35:00 | 5 times |
| 11 | CHP | CC 54 | OLR acted,5 times | reset | 04:50:00 | 05:25:00 | |
| 12 | CHP | CC 103 | fail to stop,mechanical gear box oil empty | informed mechanical | 22:35:00 | 22:45:00 | |
| 13 | CHP | CC 28 | healthy stop,cc28 and cc29 tt on 31 | cc 29 TT on31 removed | 00:40:00 | 00:55:00 | |
| 14 | CHP | CC 110 | zss acted,wrong complaint | checked and given clearance | 00:30:00 | 00:40:00 | |
| 15 | CHP | CC 44 | olr acted | reset | 22:45:00 | 22:55:00 | |
| 16 | CHP | CC 125 | olr acted | reset | 01:05:00 | 01:15:00 | |



वी.एस.पी.
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/11/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------|------------------------------|-------------------------|----------|----------|---------|
| 17 | CHP | CC 38 SCr6 | LT not working,drive tripped | reset | 01:25:00 | 01:40:00 | |
| 18 | CHP | CC 37 scr 7 | b/c not running,olr acted | reset | 01:30:00 | 01:40:00 | 2 times |
| 19 | CHP | CC 45 | olr acted | reset | 03:10:00 | 03:20:00 | 3 times |
| 20 | WT | OT 4 | initial not coming | sensor adjusted than ok | 00:30:00 | 00:45:00 | |