

RASTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT RAW MATERIAL HANDLING PLANT ELECTRICAL SHIFT REPORT

Date: 16/05/2025
Incharge(s): Saurabh Kumar Yadav,K SANKARA RAO

Shift: C

| SI No | Area | Equipment | Problem | Action | From | То | Remarks |
|----------|------|-----------------|--|---|----------|----------|---------|
| 1 | OHP | CO 35 | OLR acted | reset it done | 00:35:00 | 00:45:00 | |
| 2 | OHP | BRC on co 34 | all drive not running,ACB off condition | acb made on | 23:30:00 | 23:45:00 | |
| 3 | OHP | TBS on co 21 | LT not taking place,PCRD OT acted,overlapping of cable,guide problem | cable proper layering with mech | 01:50:00 | 02:30:00 | |
| 4 | OHP | CO 29 | OLr acted | reset it done | 03:00:00 | 03:10:00 | |
| 5 | OHP | WOBR on co 26 | all drives not running,acb is in off | acb made on | 00:30:00 | 00:50:00 | |
| 6 | OHP | BRC on co 32 | LT not taking place,PCRD OT acted | OT released | 02:15:00 | 02:25:00 | |
| 7 | OHP | VS -5A | OLR acted | reset it done | 02:00:00 | 00:21:00 | |
| 8 | CHP | CC 32 SCR 5 | LT not working,LT acted | OT released | 22:45:00 | 22:55:00 | |
| 9 | CHP | CC 36 SCR1 | LT not taking place in reverse,end limit acted | machine moved fwd than ok | 23:39:00 | 00:00:00 | |
| 10 | CHP | CC 36 SCR1 | slew not working,drive trips in overload,Tyre coupling got damaged | reset the drive,and informed mechanical | 03:39:00 | 04:10:00 | |