



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 27/05/2026

Area: IOSA

Equipment	Job
OC-7B	BELT RUPTURE SENSOR WAS FREQUENTLY ACTING. CHECKED AND FOUND H/K WAS GOING ON NEAR DECK SHEETS. CHECKED FEEDBACK
OC-15A	CABLE TRAY WELDING AND CABLE DRESSING DONE.
WOBR-FLS	AS A PART OF MANSOON JOBS, ALL FIELD DEVICES , LUFFING LIMIT SWITCHES, LT MOTOR M1 AND M3 TB COVERED WITH PLASTIC SHEET.
OFC CABLE	OFC CABLE PULLED BACK UPTO OC-6A H/E FOR OC-2A. WORK IN PROGRESS
OC-7B	PULL CHORD HARDWARE FEEDBACK INTERFACING RELAY NOT MAKING PROPER CONTACT. REPLACED.