



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 09/07/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-29	Reported tripped	OLR acted.Reset done	07:35:00	07:45:00	
2	OHP	BRC on CO-28	B/C not running	OLR acted.Reset done	08:08:00	08:18:00	
3	OHP	TBs on CO-21	Reported Lt not taking place	Drive tripped due to track jamming.Reset done	11:05:00	11:15:00	Asked operation to clear jamming
4	OHP	WOBR on CO-26	Yard signal missing	Stone stuck in cage.Removed	11:50:00	11:55:00	
5	OHP	BRC on CO-30	Shifting	Cable joint done with auxiliary shifting cable of transfer car and Lt power given and shifted to repair bay	08:00:00	11:00:00	6.6kv transformer removed to be sent to ERS
6	CHP	Cc-24	Reported tripped	Festoon cable joint insulation damaged.Taped properly and tested okay	08:40:00	09:20:00	
7	CHP	CC-52	MPD tripped	Reset done	07:46:00 12:45:00	07:48:00 12:48:00	
8	CHP	CC-107	Reported tripped	OLR acted.Reset done	06:45:00	07:52:00	
9	CHP	CC-215	Reported tripped	OLR acted.Reset done	08:15:00	08:25:00	
10	CHP	CC-32 SCR-2	LT not taking place	Drive tripped.Reset done	08:20:00 10:00:00 12:10:00	08:35:00 10:15:00 12:22:00	
11	WT	OT-3	Reported tripped	D-2 tripped on encoder fault.Reset done	11:10:00	11:15:00	