



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 28/05/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment      | Problem                                            | Action                   | From                 | To                   | Remarks  |
|-------|------|----------------|----------------------------------------------------|--------------------------|----------------------|----------------------|----------|
| 1     | OHP  | CO 26          | TRIPPED ON OLR                                     | RESET DONE               | 06:25:00             | 06:30:00             |          |
| 2     | OHP  | BRC ON CO 8A   | LT NOT TAKING PLACE/CONTROL OFF                    | CONTROL MADE ON AT CD    | 07:55:00             | 08:15:00             |          |
| 3     | CHP  | CC 51          | MPD TRIPPED ON OLR                                 | RESET DONE               | 08:40:00             | 08:45:00             |          |
| 4     | CHP  | SCR 1 ON CC31  | LT NOT TAKING PLACE/M 7 OLR ACTED                  | RESET DONE               | 09:25:00             | 09:40:00             |          |
| 5     | CHP  | SCR 2 ON CC33  | SLEW NOT TAKING PLACE/DRIVE TRIPPED ON OLR         | RESET DONE               | 11:30:00             | 11:45:00             |          |
| 6     | CHP  | SCR 5 ON CC38+ | BC STOPPING DUE TO SIGNAL MISSING                  | LT REVERSE DONE .THEN OK | 11:50:00             | 12:10:00             |          |
| 7     | WT   | OT 3           | DRIVE 2 TRIPPED ON ENCODER FAULT9( 43)             | RESET DONE 2 TIMES       | 08:50:00<br>09:05:00 | 08:55:00<br>09:10:00 |          |
| 8     | WT   | OP 9           | MIDDLE PAD C CLAMP BEND WHILE AFTER RAKE MAINTANCE | C CLAMP REPLACED .       | 12:00:00             | 12:10:00             | NO DELAY |