



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/05/2026

Shift: B

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-10A	Chute sensor not working	Fuse blown.Replaced and tested okay	15:20:00	15:30:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	18:05:00	18:12:00	
3	OHP	CO-35	Reported not healthy	E-stop stuck.Released and tested okay	15:10:00	15:20:00	
4	OHP	BRC on CO-28	LT not taking place	LT in Local.Kept in remote	15:35:00	15:50:00	
5	CHP	SCR-7 on CC-39	LT not taking place	Drive tripped.Reset done	17:20:00	17:30:00	
6	CHP	Cc-107	Reported tripped	OLR acted.Reset done	17:45:00	17:55:00	
7	CHP	Cc-37 SCR-3	LT not taking place	PCRD cable zigzag due to guide problem	20:10:00	20:30:00	Informed to mechanical. After adjustment cable winded properly
8	WT	OT-3	Reported tripped	D-2 tripped.Reset done	20:25:00	20:30:00	
9	WT	CT-2	Inhaul tripped	Reset done	15:25:00	15:30:00	
10	IOSA	FLS WOBR	LT not taking place	PCRD overtension acted.Loop given and power kept off due to H/E side reclaiming	20:10:00	20:20:00	NO delay