



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 01/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment     | Problem                                    | Action                                  | From     | To       | Remarks |
|-------|------|---------------|--------------------------------------------|-----------------------------------------|----------|----------|---------|
| 1     | OHP  | TT3 on BPC1   | position bit missing                       | bypassed at i/o rack                    | 00:25:00 | 00:30:00 |         |
| 2     | OHP  | CO 25         | OLR acted                                  | reset                                   | 00:44:00 | 00:53:00 |         |
| 3     | OHP  | CO 26         | olr acted                                  | reset                                   | 03:47:00 | 03:55:00 |         |
| 4     | CHP  | SCR2 on CC 33 | LT not working,pcrd drum fast sensor acted | reset                                   | 00:00:00 | 00:15:00 |         |
| 5     | CHP  | CC 111 R1     | b/c not running,wrong complaint            | all ok                                  | 01:25:00 | 01:35:00 |         |
| 6     | CHP  | CC 51         | mpd tripped                                | reset                                   | 03:10:00 | 03:20:00 |         |
| 7     | WT   | OT 3          | d2tripped in encoder fault                 | reset                                   | 04:20:00 | 04:30:00 |         |
| 8     | WT   | OP2           | no movement,d3 olr acted                   | reset                                   | 05:10:00 | 05:20:00 |         |
| 9     | IOSA | TBS           | communication problem                      | esteem made off and prosoft kept in ckt | 02:25:00 | 02:50:00 |         |