वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 11/10/2026

Shift: C

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | CO-25 | OLR acted | Reset done | 22:35:00 | 22:45:00 | |
| 2 | OHP | CO-26 | OLR acted | Reset done | 04:30:00 | 04:35:00 | |
| 3 | OHP | BRC ON CO-8A | LT unhealthy. Drive tripped | Reset done | 02:40:00 | 02:55:00 | |
| 4 | OHP | CO-11 | Stopping on ZSS. Found cage got struck up. | cage replaced | 22:30:00 | 23:10:00 | |
| 5 | OHP | CF-1 | Unhealthy. Found chute sensor misalignment | properly adjusted and made OK | 00:30:00 | 00:50:00 | |
| 6 | CHP | SCR-2 ON CC-33 | GVM side signal not coming. Checked and found cable got cut near to the sensor. | Bypassed and given clearance.. No delay | 22:45:00 | 23:10:00 | sensor to be checked and changed |
| 7 | CHP | SCR-5 ON CC-32 | LT unhealthy | Reset done | 03:40:00 | 03:55:00 | |
| 8 | CHP | SCR-2 ON CC-33 | Signal missing. LT done and then also signal missing. Modem ping is found OK. Ethernet cable problem found. | Spare cable laid and made ok | 03:30:00 | 04:30:00 | |
| 9 | CHP | TIS ON CC-130 | Motor tripped | Reset done | 05:35:00 | 05:40:00 | |
| 10 | CHP | CC-28 | OLR acted | Reset done | 22:20:00<br>22:50:00 | 22:25:00<br>23:00:00 | |
| 11 | CHP | CC-14 | OLR acted | Reset done | 04:05:00<br>04:20:00 | 04:10:00<br>04:30:00 | |