वी.एस.पी
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 06/11/2026

Shift: B

Incharge(s): M Kailash

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | CO-25 | Overload acted | Reset done | 15:20:00<br>21:40:00 | 15:30:00<br>21:45:00 | |
| 2 | OHP | CO-26 | overload acted | reset done | 16:00:00<br>16:20:00<br>17:50:00 | 16:05:00<br>16:25:00<br>18:00:00 | |
| 3 | OHP | TBS ON CO-19 | Left luff overload acted | Reset done | 16:40:00 | 16:55:00 | |
| 4 | OHP | CO-35 | BRS module no supply and found fuse blown in CJB. | Earth fault suspected due to JCB movement. core continuity not coming properly | 18:00:00 | 18:30:00 | to be checked further |
| 5 | CHP | CC-215 | Overload acted | Reset done | 15:50:00 | 16:05:00 | |
| 6 | CHP | CC-107 | overload acted | Reset done | 18:00:00 | 18:10:00 | |
| 7 | CHP | RECL-1 ON CC-36 | Slew not working. checked and found working | . | 18:30:00 | 18:40:00 | wrong complaint |
| 8 | CHP | SCR-1 ON CC-31 | PLC went to stop mode. | power recycle done and made OK | 18:30:00 | 18:50:00 | |
| 9 | CHP | CC-54 | overload acted | Reset done | 19:50:00<br>20:05:00 | 19:55:00<br>20:10:00 | |