



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL GENERAL SHIFT REPORT**

Date: 15/05/2026

Area: OHP

| Equipment                    | Job                                                                                             |
|------------------------------|-------------------------------------------------------------------------------------------------|
| brc-2 on co-30               | preparation work for ht transformer oil leak job is done                                        |
| co-10,2a                     | field devices cables along the conveyor inspection is done and found ok.                        |
| co-10,13,15,tt-2             | motor and panel side ppm is done.                                                               |
| Failed Sump pump motors      | 4 sump pumps sent to ers for rectification.                                                     |
| co-65,66,67 h/e area         | cctv supply purpose cable is laid.                                                              |
| 1-141lc4, om-16, om-24,om-15 | earth pits testing and defects recorded.                                                        |
| rsco-1a, rbf-1a,2a           | motor side ppm is done.                                                                         |
| cr-2a                        | motor and panel side ppm is done                                                                |
| brc-4 on co-8a               | bw-1 was stopping on increase of load, checked no fault found electrically, informed operation. |
| 110kw hydraulic pump motor   | spare motor found low megger values, sent to ers for overhauling.                               |
| io-8,7                       | lighting is improved near the isolator panels.                                                  |
| om-12,lc-8,om-16,12          | earth pit inspection is done and defects recorded.                                              |
| co-21                        | electronic brs checked, mechanical brs sensor is checked and restored both brs in series.       |