



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/05/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-10A	CJD towards sinter plant not healthy	Bypassed and checked and found cable insulation damaged.Rectified and kept in line	16:35:00	19:45:00	
2	OHP	CO-50	Reported tripped	OLR acted.Reset done	15:46:00	15:54:00	
3	OHP	CC-51	MPD tripped	Reset done.	18:05:00	18:10:00	
4	OHP	TBS on CO-7A	LT not taking place	Wrong complaint	17:30:00	17:45:00	
5	OHP	CO-26	Reported tripped	OLR acted.Reset done(3 times)	17:45:00	20:20:00	
6	OHP	CO-25	Reported not running	TIS feedback bypass wire loose.Tightened and tested okay	17:45:00	18:00:00	
7	OHP	BRC on CO-28	B/C not running	OLR acted due to heavy material on belt.Reverse direction run after for cleaning purpose and again kept in normal after clearing material.	19:35:00	21:50:00	
8	CHP	CC-52	MPD tripped	Reset done	18:10:00	18:15:00	
9	CHP	CC-53	BSS acted	BSS acted.Reset done	17:15:00	17:25:00	
10	WT	OP-4	Reported tripped	D-3 OLR acted.Reset done and tested okay.Wagon sensor bypassed	16:00:00	16:30:00	