# RASHTRIYA ISPAT NIGAM LIMITED

## VISAKHAPATNAM STEEL PLANT

### RAW MATERIAL HANDLING PLANT

### ELECTRICAL SHIFT REPORT

Date: 12/11/2026

Shift: B

Incharge(s): Nagendra Midde

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|---|---|---|---|---|---|---|---|
| 1 | OHP | CO-25 | overload acted | Reset done | 18:22:00 | 18:30:00 | |
| 2 | OHP | CO-5A | BRS acting frequently. checked and found OK | . | 21:30:00 | 21:40:00 | |
| 3 | CHP | STK-2 ON CC-112 | B/C not running. MPR tripped | Reset done | 14:25:00 | 14:40:00 | |
| 4 | CHP | SCR-1 ON CC-31 | Slew not working. Found slew drive tripped | reset done | 17:30:00 | 17:45:00 | |
| 5 | CHP | CC-108 | overload tripped | Reset done | 17:00:00<br>20:45:00 | 17:05:00<br>20:50:00 | |
| 6 | CHP | SCR-6 ON CC-38 | slew not working. slew area coal jamming. | informed to operation | 19:35:00 | 19:50:00 | |
| 7 | CHP | SCR-3 ON CC-106 | B/C not running in GVM side. checked and found COB-5 HMI bed selection not proper | Made proper selection and checked OK | 18:35:00 | 19:10:00 | |
| 8 | CHP | SCR-3 ON CC-106 | LT not working. Drive tripped | Reset done | 21:20:00 | 21:35:00 | |
| 9 | CHP | CC-131 | overload tripped | Reset done | 18:15:00<br>20:40:00 | 18:20:00<br>20:45:00 | |
| 10 | CHP | CC-54, CC-130,CC-131 | Belt sway bits became RED. checked in PLC and found no complaint | checked in field and found Belt sway switches acted. Released | 19:10:00 | 19:40:00 | |
| 11 | WT | OP-3 | No movement. Found D-5 rotor contactor stuck up. | contactor opened and cleaned. | 14:00:00 | 14:15:00 | |