वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 06/11/2026

Shift: B

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Overload acted	Reset done	15:20:00 21:40:00	15:30:00 21:45:00	
2	OHP	CO-26	overload acted	reset done	16:00:00 16:20:00 17:50:00	16:05:00 16:25:00 18:00:00	
3	OHP	TBS ON CO-19	Left luff overload acted	Reset done	16:40:00	16:55:00	
4	OHP	CO-35	BRS module no supply and found fuse blown in CJB.	Earth fault suspected due to JCB movement. core continuity not coming properly	18:00:00	18:30:00	to be checked further
5	CHP	CC-215	Overload acted	Reset done	15:50:00	16:05:00	
6	CHP	CC-107	overload acted	Reset done	18:00:00	18:10:00	
7	CHP	RECL-1 ON CC-36	Slew not working. checked and found working	.	18:30:00	18:40:00	wrong complaint
8	CHP	SCR-1 ON CC-31	PLC went to stop mode.	power recycle done and made OK	18:30:00	18:50:00	
9	CHP	CC-54	overload acted	Reset done	19:50:00 20:05:00	19:55:00 20:10:00	