



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL GENERAL SHIFT REPORT

Date: 29/06/2026

Area: OHP

Equipment	Job
co-30,31,32,31a,33a,35a,65,66,67	chute vibrators inspection is done.
co-30,31,32,31a,33a,35a,65,66,67	chute vibrators inspection is done.
co-57 gallery, vs-2 level	lighting is improved.
co-57 gallery, vs-2 level	lighting is improved.
ZSS cage preparation	4 no.'s spare made ready at HVMCC-1
ZSS cage preparation	4 no.'s spare made ready at HVMCC-1
tbs-6 on co-7a	chute vibrator lug got cut,, re lugged and restored operation.
tbs-6 on co-7a	chute vibrator lug got cut,, re lugged and restored operation.
tbs-7 on co-19	CRMP side thruster brake is replaced with spare one, overhauling of removed motor needs to be done.
tbs-7 on co-19	CRMP side thruster brake is replaced with spare one, overhauling of removed motor needs to be done.
co-17,18 H/E	hoist, LDb panel maintenance is done.
co-17,18 H/E	hoist, LDb panel maintenance is done.
co-3a,3b,14,15 ; cr-1a,3a	vibration reading are recorded.
co-3a,3b,14,15 ; cr-1a,3a	vibration reading are recorded.
JH O-3 gallery; co-59 galelry, 62 floor,,,: CO- 8a ,db-1,bpc-1,bpc-2,28,27a,30a H/E, gallery	lighting inspection is done.
JH O-3 gallery; co-59 galelry, 62 floor,,,: CO- 8a ,db-1,bpc-1,bpc-2,28,27a,30a H/E, gallery	lighting inspection is done.
co-11 to co-16 chute vibrator	not working due to lug damage, re lugged and restored operation.



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL GENERAL SHIFT REPORT

Date: 29/06/2026

Area: OHP

Equipment	Job
co-11 to co-16 chute vibrator	not working due to lug damage, re lugged and restored operation.
brc-3 on co-34; co-15a,41a,42a,43a; vf-8a,9a,10a,15a,16a	motor and panel side ppm is done.
brc-3 on co-34; co-15a,41a,42a,43a; vf-8a,9a,10a,15a,16a	motor and panel side ppm is done.
co-8 brs	checked, sensors cleaned and restored in circuit.
co-8 brs	checked, sensors cleaned and restored in circuit.
wobr-2 on co-29	LT brake CHP side, coil problem is found, brake panel also voltage is not available. further checking needs to be done.
wobr-2 on co-29	LT brake CHP side, coil problem is found, brake panel also voltage is not available. further checking needs to be done.