



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 13/08/2026

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment    | Problem                           | Action                                            | From     | To       | Remarks                        |
|-------|------|--------------|-----------------------------------|---------------------------------------------------|----------|----------|--------------------------------|
| 1     | OHP  | OT-3         | Motor drive end cover bolts loose | Bolts tightened and tested okay                   | 15:00:00 | 15:15:00 |                                |
| 2     | OHP  | CO-51        | Reported tripped                  | OLR acted.Reset done                              | 15:00:00 | 15:08:00 |                                |
| 3     | OHP  | CO-26        | Reported tripped                  | ORL acted.Reset done(3 times)                     | 16:50:00 | 19:35:00 |                                |
| 4     | OHP  | BRC on CO-8A | Yard interlock signal missing     | Interlock yard ZSS probe problem                  | 20:00:00 | 22:00:00 | TO be changed when CO-8A stops |
| 5     | CHP  | CC-132       | Reported PC not healthy           | LR PC acted.Reset done and tested okay            | 16:30:00 | 16:40:00 |                                |
| 6     | CHP  | CC-33 SCR-2  | LT not taking place               | PCRD drum sensor acted.Reset done and tested okay | 19:10:00 | 19:25:00 |                                |
| 7     | WT   | OC-1A        | ZSS acted                         | Found material jamming                            | 21:00:00 | 21:15:00 |                                |