



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 08/05/2026

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment     | Problem                     | Action                                                                                                       | From                 | To                   | Remarks                                                                              |
|-------|------|---------------|-----------------------------|--------------------------------------------------------------------------------------------------------------|----------------------|----------------------|--------------------------------------------------------------------------------------|
| 1     | OHP  | WOBR on CO-29 | B/W not running             | Motor meggered and made to run and smoke came out.Placement done for motor replacement and spare motor found | 06:30:00             | 07:45:00             | Motor replaced and clearance given at 12.10PM                                        |
| 2     | OHP  | CO-26         | Reported tripped            | OLR acted.Reset done(2 times)                                                                                | 06:30:00<br>08:10:00 | 06:35:00<br>08:15:00 |                                                                                      |
| 3     | OHP  | BRC on CO-8A  | CT not taking place         | MCCB in off condition.Made on                                                                                | 08:45:00             | 08:55:00             |                                                                                      |
| 4     | OHP  | WOBR on CO-26 | Slewing not taking place    | Drive tripped.Reset done                                                                                     | 09:05:00             | 09:15:00             |                                                                                      |
| 5     | CHP  | Cc-54         | Reported tripped            | OLR acted due to decksheet jamming.Reset done(5 times)                                                       | 11:15:00             | 12:00:00             |                                                                                      |
| 6     | CHP  | CC-201        | Reported PC and Control off | Checked and found PC contact missing.Bypassed and given clearance                                            | 08:30:00             | 09:00:00             | After checking found 3 Pc's were in operated condition.Reset done and bypass removed |
| 7     | CHP  | CC-25,26,27   | Reported not healthy        | I/O rack 110V MCB tripped.Made on                                                                            | 06:30:00             | 06:50:00             |                                                                                      |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 08/05/2026

Incharge(s): Amit Roy

Shift: A

| Sl No | Area | Equipment      | Problem             | Action                                                                      | From     | To       | Remarks                |
|-------|------|----------------|---------------------|-----------------------------------------------------------------------------|----------|----------|------------------------|
| 8     | CHP  | CC-203         | Reported tripped    | OLR acted.Reset done                                                        | 08:30:00 | 08:40:00 |                        |
| 9     | CHP  | Cc-218         | Reported tripped    | OLR acted.Reset done                                                        | 10:15:00 | 10:25:00 |                        |
| 10    | CHP  | CC-33<br>SCR-2 | Luffing not working | Oil temperature high.Bypassed at I/O rack.                                  | 12:55:00 | 13:10:00 | Informed to mechanical |
| 11    | CHP  | Cc-40          | Reported tripped    | Checked and found soft hard relay problem.replaced with new and tested okay | 11:30:00 | 13:00:00 |                        |