



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 07/09/2026

Incharge(s): K SANKARA RAO

Shift: A

| Sl No | Area | Equipment   | Problem                                                                                      | Action                 | From                 | To                   | Remarks |
|-------|------|-------------|----------------------------------------------------------------------------------------------|------------------------|----------------------|----------------------|---------|
| 1     | OHP  | CO-34       | OLR ACTED (2TIMES)                                                                           | RESET DONE             | 08:10:00<br>08:30:00 | 08:15:00<br>08:35:00 |         |
| 2     | OHP  | CO-20       | REPORTED FAIL TO START CHECKED AND FOUND OUT PUT COMMEND RELAY COIL WIRE LOOSE               | PROPERLY TIGHT THAN OK | 11:45:00             | 12:05:00             |         |
| 3     | OHP  | OF-1, 68A   | REPORTED RUN FEEDBACK NOT COMING IN OCR CHECKED AND FOUND 1-15LC-2 RIO PANEL HIGH WIRE LOOSE | PROPERLY TIGHT THAN OK | 13:30:00             | 14:00:00             |         |
| 4     | CHP  | CC-33.SCR-5 | REPORTED LT NOT TAKING PLACE FOUND PCRD O/T ACTED                                            | RELEASED THAN OK       | 06:45:00             | 07:00:00             |         |
| 5     | CHP  | CC-36 SCR-3 | REPORTED LT NOT TAKING PLACE FOUND DRIVE TRIP (OVN FAULT)                                    | RESET DONE             | 11:45:00             | 12:00:00             |         |